



Service bulletin

C. 251

THE BRITISH MOTOR CORPORATION (AUSTRALIA) PTY. LIMITED


FOR THE ATTENTION OF SERVICE & PARTS MANAGERS

DISC BRAKES

When refitting disc brake pistons to the caliper housing, care should be taken to see that the cutaway part of the piston faces downwards as shown at 'A' (left hand caliper drawn.)

CARS

Healey
Sprite
MK. IIA



N. Prescott,
Service Manager.

A/519

25. 10. 63.