



Service bulletin

C. 270

THE BRITISH MOTOR CORPORATION (AUSTRALIA) PTY. LIMITED

FOR THE ATTENTION OF SERVICE & PARTS MANAGERS.


DISC BRAKE CALLIPER PISTON POSITIONS

In view of the varying positions of the piston cut-away portion on disc brake calliper assemblies fitted to different models, the following illustrations may be used for guidance where the appropriate Workshop Manual is not specific.

DIRECTION OF TRAVEL



ALL DISC
BRAKED
MODELS




MGB

A99, W6/99,
W6/110, A110,
3-Litre Princess.

Mini Cooper &
Cooper 'S'

Healey 3000



M.1100

A. H. Sprite

M. G. A. 1600

GN/184
25. 5. 64
Page 1 of 1

N. Prescott
N. Prescott
Service Manager